

Dacia Sandero

Stepway 1.0 Gasoline 91hp

Gasoline - Manual - 37614km - 02/2021

Ref 55579



[All images](#)

Dacia Sandero

Stepway 1.0 Gasoline 91hp

Gasoline - Manual - 37614km - 02/2021

Ref 55579

Description

Make	Dacia
Model	Sandero
Description	Stepway 1.0 Gasoline 91hp
Mileage	37614 km
Type	Passenger car
Body type	Compact / Citycar
Doors	5
Seats	5
Exterior color	White
Interior color	Other
Upholstery	Cloth

Technical

Fuel type	Gasoline	Gears	6
Gearbox	Manual	Cylinders	0
Cylinder capacity	999 cc	Horse power	92 hp
Power KW	67 kw		
Drive train	Front		

Dimensions

Weight empty	1152 kg		
Length	408 cm		
Height	149 cm	Width	184 cm

Dacia Sandero

Stepway 1.0 Gasoline 91hp

Gasoline - Manual - 37614km - 02/2021

Ref 55579

Registration and Warranty

First Registration 10-02-2021

Options

Comfort

Central locking

Sensor interior light

Start/stop system

Safety

ABS

Cruise control

ESP

Isofix

Lights LED daytime running

Speed limit control system

Traction control

Infotainment

Bluetooth

DAB radio

Hands-free equipment

On-board computer

Radio

USB

Voice control

Extras

Roof rack

Tires winter

Dacia Sandero

Stepway 1.0 Gasoline 91hp

Gasoline - Manual - 37614km - 02/2021

Ref 55579

Equipment

ASC (traction control)	Speed limiter
ESP	Checkbook maintained
Partial LED headlights	Non-smoking vehicle.
Voice control.	Height-adjustable steering wheel
Power steering	Stability control
Automatic start/stop	Front fog lights
Central locking with radio	Roof rails
Winter tires	Driver airbag
Passenger airbag.	Cruise control system
LED daytime running lights	Heated rear window
Passenger airbag can be deactivated	USB connection
Electric immobilizer	Child seat preparation (ISOFIX)
On-board computer	ABS
Radio	5 head restraints
Hands-free system	DAB Receiver.
Bluetooth	ASR (traction control)
Driver/passenger airbag	Upholstery fabric
Light sensor	Air conditioning.

Image gallery




































JUSTIFICATIVE DE ÎNTREȚINERE (2/6)

Număr de indentificare vehicul (VIN):

Data: 06.12.2024 Km: 29500




Tip de intervenție:	Stampilă	Nr. factură:	Comentarii/diverse
Revizie <u>4 ANI</u> <input type="checkbox"/> Control anticorozioane: OK <input type="checkbox"/> Nu e OK* <input type="checkbox"/> <small>*Consultați pagina respectivă</small>	ULEI FULGI BULII CURȚĂ ACE FAER 		
Data: Km: Tip de intervenție: Revizie <input type="checkbox"/> Control anticorozioane: OK <input type="checkbox"/> Nu e OK* <input type="checkbox"/> <small>*Consultați pagina respectivă</small>	Stampilă		
Data: Km: Tip de intervenție: Revizie <input type="checkbox"/> Control anticorozioane: OK <input type="checkbox"/> Nu e OK* <input type="checkbox"/> <small>*Consultați pagina respectivă</small>	Stampilă		

6.12

JUSTIFICATIVE DE ÎNTREȚINERE (1/6)

Număr de identificare vehicul (VIN): UW1DJF00186957274

Data: 05.12.2022 Km: 6618 Nr. factură:

Tip de intervenție: Revizie: <u>U.M.N.</u> <input checked="" type="checkbox"/> Control anticoroziiune: OK <input type="checkbox"/> Nu e OK* <input type="checkbox"/> *Consultați pagina respectivă	Stampilă Ulei motor în Huu ulei 	Comentarii/observații
Data: <u>11.12.2022</u> Km: <u>14288</u> Nr. factură: Tip de intervenție: Revizie: <u>3 ANI</u> <input checked="" type="checkbox"/> Control anticoroziiune: OK <input checked="" type="checkbox"/> Nu e OK* <input type="checkbox"/> *Consultați pagina respectivă	Stampilă ulei motor + filtre + aer + habitaclu 	Comentarii/observații
Data: <u>12.12.2023</u> Km: <u>21750</u> Nr. factură: Tip de intervenție: Revizie: <u>3 ANI</u> <input checked="" type="checkbox"/> Control anticoroziiune: OK <input type="checkbox"/> Nu e OK* <input type="checkbox"/> *Consultați pagina respectivă	Stampilă ulei motor + filtre 	Comentarii/observații

6.11

